



7. Curvas

7.1 Curvas de disparo (temperatura ambiente +40°C)


NM8-125(16A, 20A)




NM8-125(25A, 32A)




NM8-125(40A, 50A)




NM8-125(63A)




NM8-125(80A,100A)




NM8-125(125A)




NM8-250(100A)




NM8-250(160A)




NM8-125(80A,100A)




NM8-125(125A)



NM8-800, 1250(630A~800A)




NM8-800, 1250(800A~1250A)




7.2 Curvas de disparo aparatos electrónicos


NM8S-125, NM8S-250(40A~250A)



NM8S-400, NM8S-630(250A~630A)



NM8S-800, NM8S-1250(630A~1250A)



Protección de motores - NM8M-125, 250, 400, 630(16A~500A)

